

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

| Representativ | es Present During the Inspection: | |
|----------------|---------------------------------------|--|
| rtoprosontativ | cs r resent builing the inspection. | |
| OGM | Pete Hess Environmental Scientist III | |
| Company | David Shaver Manager | |

Inspection Report

| Permit Number: | | | |
|------------------|---------------------------|--|--|
| Inspection Type: | | | |
| Inspection Date: | Monday, December 15, 2008 | | |
| Start Date/Time: | 12/15/2008 8:30:00 AM | | |
| End Date/Time: | 12/15/2008 9:35:00 AM | | |
| Last Inspection: | Friday, November 28, 2008 | | |

Inspector: Pete Hess, Environmental Scientist III
Weather: Overcast, cold; 20's F. Snow forecast.

InspectionID Report Number: 1863

Accepted by: Jhelfric 1/6/2009

Permitee: ANDALEX RESOURCES INC TOWER DIVISION
Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

| 100.00 | Total Permitted | |
|--------|------------------------|--|
| 63.70 | Total Disturbed | |
| | Phase I | |
| | Phase II | |
| | Phase III | |

Mineral Ownership

Federal

State

County

☐ Underground
☐ Surface
✔ Loadout

Types of Operations

☐ Fee☑ Processing☐ Other☑ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The UDOGM water monitoring data base contains surface water monitoring information for the third quarter 2008 for the Wildcat permit area. The Permittee is current relative to this Special Condition of Attachment "A" of the State permit.

Inspector's Signature:

Date

Monday, December 15, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, December 15, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | | | | |
| 2. | Signs and Markers | ✓ | | | |
| 3. | Topsoil | | | | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ✓ | | ✓ | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | | | | |
| 4.d | Hydrologic Balance: Water Monitoring | | | | |
| 4.e | Hydrologic Balance: Effluent Limitations | | | | |
| 5. | Explosives | | ✓ | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | ✓ | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | ✓ | | ✓ | |
| 8. | Noncoal Waste | ✓ | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | ✓ | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | ✓ | | |
| 13. | Revegetation | | ✓ | | |
| 14. | Subsidence Control | | ✓ | | |
| 15. | Cessation of Operations | | ✓ | | |
| 16.8 | Roads: Construction, Maintenance, Surfacing | V | | ✓ | |
| 16.t | Roads: Drainage Controls | V | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | V | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | V | | V | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Permit Number: C0070033
Inspection Type: PARTIAL

Inspection Date: Monday, December 15, 2008

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds "D", "E", and "F" were dry; pond "C" was frozen, with the ice level well below the discharge elevation. There were no compliance issues identified.

7. Coal Mine Waste, Refuse Piles, Impoundments

The coal waste disposal pile is being maintained according to the approved design. Noncoal waste material was not visible within the top lift of material. The outslopes were well shaped, with no sign of erosion.

16.a Roads: Construction, Maintenance, Surfacing

All operational roads were well graded; there were no potholes observed.

20. Air Quality Permit

The ambient air temperature was below freezing. Haul trucks entering and leaving the disturbed area were adhering to the post 5 MPH speed limit. There was no visible dust behind the trucks.